To JO-1MDW users with firmware version 2.24

Please upgrade the firmware version from 2.24 to 2.25 manually.

Version 2.24 may occur disconnection with Wireless LAN connection.

The automatic update function does not work due to software bugs. Please update manually from the NOTIFICATION screen by tapping the "ⓘ" icon on the MENU screen.

Use this method when updating the station manually.

1 From the MENU screen, tap ⓘ.

The notification list will be shown.

2 Tap Check of the notification "New firmware available.".


A message will appear to ask whether you will update the station.

3 To update, tap ✓.

4 Tap ✓.

The updating begins.

When "The firmware has been updated. The station will restart in 5 sec." is shown, the update has been completed, and the station reboots after 5 seconds.